DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR3KAHPY6 TS031213	Registration date	02/02/2026	Exterior Color	Artens Grijs
Brand	PEUGEOT	Licence Plate	00xx00	Odometer	25 017 km
Model	NEW 3008 ALLURE Hybrid 145 ch e-DSC6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond



Removable element


Emergency compressor kit	✖
Refill emergency kit	✖

Technical Document

Tyres

Michelin 225/55/18 V Summer 6.0 mm

Michelin 225/55/18 V Summer 6.0 mm





Michelin 225/55/18 V Summer 7.0 mm

Michelin 225/55/18 V Summer 7.0 mm

Exterior

1




Part	Refill emergency kit
Position	-
Damages	Missing
Comments	-

2



Part	Emergency compressor kit
Position	-
Damages	Missing
Comments	-

4



Part	Tailgate / Boot door
Position	-
Damages	Scratched
Comments	-

5



Part	Door sill
Position	Front left
Damages	Dented
Comments	-


6



Part	Bumper moulding
Position	-
Damages	Stone impact
Comments	-

Interior damage

3



Part	Interior cleaning
Position	-
Damages	Not carried out
Comments	-