DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	VR1JCYHZ6 SY547203	Registration date	14/05/2025	Exterior Color	Gris Laqu
Brand	DS	Licence Plate	1ADS527	Odometer	12 562 km
Model	DS 7 BLUEHDI 130 AUTOMATIC ETOILE	Condition of the car	Condition of use		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Parc LLD



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
In-car tools	✓
Toolkit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Towing hook	✓
Adjustable Boot Space	✓


Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Adapter USB	✓
Spare key	✓
Card Key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres

Michelin 235/50/19 V Summer 6.0 mm

Michelin 235/50/19 V Summer 6.0 mm





Michelin 235/50/19 V Summer 7.0 mm

Michelin 235/50/19 V Summer 7.0 mm

Exterior

1



Part	Bumper
Position	Front right
Damages	Scratched
Comments	-

2



Part	Spoiler
Position	Front
Damages	Scratched
Comments	-

3



Part	Special rim 19"
Position	Front left
Damages	Scratched
Comments	-

4



Part	Wing
Position	Back right
Damages	Scratched
Comments	-

6



Part	Special rim 19"
Position	Back right
Damages	Scratched
Comments	-

7



Part	Special rim 19"
Position	Front right
Damages	Scratched
Comments	-

Interior damage

5



Part	Leather seat
Position	Front right
Damages	Stained/dirty
Comments	-