DEKRA

DEKRA Automotive Solutions

Appraisal Report


STELLANTIS

Vehicle details

VIN	VR1J45GB9 SY603862	Registration date	24/11/2025	Exterior Color	Noir Perla Nera
Brand	DS	Licence Plate	2HVE484	Odometer	213 km
Model	DS 7 PLUG-IN HYBRID AWD 360 PERFORMANCE	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond



Removable element

Spare wheel kit	✔
Rear parcel shelf	✔

Technical Document

Tyres

Michelin 245/35/21 Y Summer 7.0 mm		Michelin 245/35/21 Y Summer 7.0 mm	
Michelin 245/35/21 Y Summer 7.0 mm		Michelin 245/35/21 Y Summer 7.0 mm	

Exterior

1



Part	Rear window tinted
Position	-
Damages	Sticker marked
Comments	-