DEKRA Automotive Solutions

# Appraisal Report

STELLANTIS

## Vehicle details

| | | | | | |
|---|---|---|---|---|---|
| VIN | VR7CCHPV8 TT031811 | Registration date | 12/02/2026 | Exterior Color | Perla Nera Black (pa |
| Brand | CITROEN | Licence Plate | | Odometer | 14 847 km |
| Model | C3 Turbo 100 ch Manual MAX | Condition of the car | Unknown | | |
| Pre-damage | Unknown | Pre-damage amount excl. VAT | - | Pre-damage Comments | |

## Inspection Details

| | |
|---|---|
| Inspection loc. | PCD - Hödlmayr Saint-Trond |















## Removable element


| | |
|---|---|
| Emergency compressor kit | ✖ |
| Refill emergency kit | ✖ |

## Technical Document

## Tyres

Goodyear 205/50/17 V Summer 5.0 mm

Goodyear 205/50/17 V Summer 5.0 mm



Goodyear 205/50/17 V Summer 6.0 mm

Goodyear 205/50/17 V Summer 6.0 mm

## Exterior

**2**



| | |
|---|---|
| Part | Emergency compressor kit |
| Position | - |
| Damages | Missing |
| Comments | - |

**3**



| | |
|---|---|
| Part | Refill emergency kit |
| Position | - |
| Damages | Missing |
| Comments | - |

**4**



| | |
|---|---|
| Part | Bonnet |
| Position | - |
| Damages | Chemical deposit |
| Comments | - |

**6**



| | |
|---|---|
| Part | Door |
| Position | Front right |
| Damages | Dented |
| Comments | - |

**7**



| | |
|---|---|
| Part | Tailgate / Boot door |
| Position | - |
| Damages | Improper repair |
| Comments | schuurkrassen en slechte voorbereiding |

**8**



| | |
|---|---|
| Part | Tailgate / Boot door badge |
| Position | - |
| Damages | Missing |
| Comments | - |

## Interior damage

**5**



| | |
|---|---|
| Part | Interior cleaning |
| Position | - |
| Damages | Not carried out |
| Comments | - |

## Others

**1**



| | |
|---|---|
| Part | Fuel lumpsum |
| Position | - |
| Damages | Missing |
| Comments | - |