DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR1FNZKZ5 S1035844	Registration date	06/10/2025	Exterior Color	Cristal Pearl
Brand	DS	Licence Plate	2HRY026	Odometer	4 920 km
Model	N°4 E-TENSE 215 ETOILE ALCANTARA	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Triangle	✓
Safety vest	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Fire extinguisher	✓
Towing hook	✓


Technical Document

Service manual holder	✓
First aid kit	✓
Spare key	✓
Remote key	✓

Tyres

Michelin 225/50/19 V Summer 7.0 mm

Michelin 225/50/19 V Summer 7.0 mm



Michelin 225/50/19 V Summer 7.0 mm

Michelin 225/50/19 V Summer 7.0 mm



Others

1

Part	Damage appraisal
Position	-
Damages	Clear
Comments	-