DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR1F4DGNX S1055700	Registration date	11/02/2026	Exterior Color	Vol de Nuit
Brand	DS	Licence Plate	2JFX080	Odometer	7 090 km
Model	N°4 PLUG-IN HYBRID 225 ETOILE NAPPA	Condition of the car	Repaired after accident		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
In-car tools	✓
Toolkit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Towing hook	✓
Vehicle charger	✗


Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Adapter USB	✓
Spare key	✓
Card Key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres

Michelin 205/55/19 V Summer 5.0 mm

Michelin 205/55/19 V Summer 5.0 mm



Michelin 205/55/19 V Summer 6.0 mm

Michelin 205/55/19 V Summer 6.0 mm

Exterior

1



Part	Exterior complete
Position	-
Damages	Not conform
Comments	Conditions d'expertise...

2



Part	Door
Position	Back left
Damages	Scratched
Comments	-

3




Part	Bumper
Position	Back left
Damages	Scratched
Comments	-

5



Part	Special rim 19"
Position	Back right
Damages	Scratched
Comments	-

6



Part	Door exterior lower moulding
Position	Back right
Damages	Scratched
Comments	Superficiel

7



Part	Other bodywork
Position	Side right
Damages	Repaired
Comments	Flanc

8



Part	Special rim 19"
Position	Front right
Damages	Stained/dirty
Comments	-

9



Part	Headlight
Position	Front right
Damages	Repaired
Comments	Nouveau

10



Part	Wing
Position	Front right
Damages	Repaired
Comments	Pointe pas fixée comme celle d'origine...


11



Part	Lower door
Position	Front left
Damages	Scratched
Comments	-

Others

4



Part	Vehicle charger
Position	-
Damages	Missing
Comments	-

Comments

Réserve teinte limite flanc D