DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR7KAHPY7 SL029509	Registration date	01/01/1900	Exterior Color	Unknown
Brand	CITROEN	Licence Plate		Odometer	10 208 km
Model	C5 AIRCROSS	Condition of the car	Condition of use		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
In-car tools	✓
Toolkit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Towing hook	✓
Adjustable Boot Space	✓


Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Adapter USB	✓
Spare key	✓
Card Key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres

Michelin 225/55/19 V Summer 5.0 mm

Michelin 225/55/19 V Summer 5.0 mm





Michelin 225/55/19 V Summer 6.0 mm

Michelin 225/55/19 V Summer 6.0 mm

Exterior

1



Part	Exterior complete
Position	-
Damages	Not conform
Comments	Conditions expertise

2



Part	Roof
Position	-
Damages	Chemical deposit
Comments	-

3



Part	Bonnet
Position	-
Damages	Chemical deposit
Comments	25€ S.R.

4



Part	Bumper
Position	Back left
Damages	Improper repair
Comments	-

5



Part	Door
Position	Front right
Damages	Dented
Comments	-