DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR7KAHPY9 SL039426	Registration date	01/01/1900	Exterior Color	Unknown
Brand	CITROEN	Licence Plate	2HPA862	Odometer	8 556 km
Model	C5 AIRCROSS	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond



Removable element

Triangle	✓
Safety vest	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Fire extinguisher	✓
Sun visor exterior	✓
Aerial cable	✓
Spare wheel kit	✗
Emergency compressor kit	✗

Technical Document

Service manual holder	✓
User manual	✓
First aid kit	✓
Adapter USB	✓
Spare key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres

Michelin 225/55/19 V Summer 7.0 mm		Michelin 225/55/19 V Summer 7.0 mm
Michelin 225/55/19 V Summer 7.0 mm		Michelin 225/55/19 V Summer 7.0 mm

Exterior

1



Part	Special rim 19"
Position	Front right
Damages	Scratched
Comments	-

2



Part	Refill emergency kit
Position	-
Damages	Missing
Comments	-

3



Part	Emergency compressor kit
Position	-
Damages	Missing
Comments	-