DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR7KCZKZ9 SL053343	Registration date	01/01/1900	Exterior Color	Unknown
Brand	CITROEN	Licence Plate	2HUH564	Odometer	4 821 km
Model	C5 AIRCROSS	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Triangle	✓
Safety vest	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Fire extinguisher	✓
Towing hook	✓


Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
First aid kit	✓
Spare key	✓
Remote key	✓

Tyres

Michelin 235/50/20 V Summer 7.0 mm

Michelin 235/50/20 V Summer 7.0 mm





Michelin 235/50/20 V Summer 7.0 mm

Michelin 235/50/20 V Summer 7.0 mm

Exterior

1



Part	Bumper
Position	Back
Damages	Dented
Comments	-

DEKRA Automotive Solutions

STELLANTIS

Comments

Parc stockage : PCD - Parc LLD