DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR3USHPY7 SJ936862	Registration date	08/12/2025	Exterior Color	Selenium Grijs
Brand	PEUGEOT	Licence Plate		Odometer	17 260 km
Model	2008 Allure 1.2 Hybrid 145 ch e-DCS6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond















Removable element


Emergency compressor kit	✖
Refill emergency kit	✖

Technical Document

Tyres

Goodyear 215/60/17 H All seasons 6.0 mm

Goodyear 215/60/17 H All seasons 6.0 mm



Goodyear 215/60/17 H All seasons 7.0 mm

Goodyear 215/60/17 H All seasons 7.0 mm

Exterior

1



Part	Engine soundproofing
Position	-
Damages	Missing
Comments	bevestiging is nog aanwezig

2



Part	Emergency compressor kit
Position	-
Damages	Missing
Comments	-

3



Part	Refill emergency kit
Position	-
Damages	Missing
Comments	-

4



Part	Door
Position	Front left
Damages	Dented
Comments	-

5



Part	Bonnet
Position	-
Damages	Stone impact
Comments	-