DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR3KAHPY7 SS175349	Registration date	10/12/2025	Exterior Color	Perla Nera Zwart
Brand	PEUGEOT	Licence Plate	2HWX374	Odometer	4 901 km
Model	New 3008 GT Hybrid 145 e-DSC6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond
















Removable element

Emergency compressor kit	✓
Refill emergency kit	✓

Technical Document


Service manual holder	✓
User manual	✓
Spare key	✓
Key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres

Michelin 225/55/19 V Summer 6.0 mm

Michelin 225/55/19 V Summer 6.0 mm





Michelin 225/55/19 V Summer 7.0 mm

Michelin 225/55/19 V Summer 7.0 mm

Exterior

1



Part	Door
Position	Back right
Damages	Scratched
Comments	-

3



Part	Door
Position	Back right
Damages	Scratched
Comments	-

4



Part	Door sill
Position	Back right
Damages	Dent & Chips
Comments	-

Interior damage

2



Part	Interior cleaning
Position	-
Damages	Not carried out
Comments	-

5

Part	Rear side interior trim panel
Position	Back left
Damages	Scratched
Comments	-