DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR7CCHPX8 ST208664	Registration date	13/10/2025	Exterior Color	Bright Blue (mtallis
Brand	CITROEN	Licence Plate	2HSX026	Odometer	5 320 km
Model	New C3 Hybrid 110 ch Automatic MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Towing hook	✓
Aerial cable	✓

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓
Remote key	✓

Tyres

Goodyear 205/50/17 V Summer 7.0 mm

Goodyear 205/50/17 V Summer 7.0 mm



Goodyear 205/50/17 V Summer 7.0 mm

Goodyear 205/50/17 V Summer 7.0 mm

Exterior

1



Part	Special rim 17"
Position	Front right
Damages	Scratched
Comments	-

2



Part	Special rim 17"
Position	Back left
Damages	Scratched
Comments	-