DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR1J45GB2 SY548655	Registration date	24/11/2025	Exterior Color	Gris Laqu
Brand	DS	Licence Plate	N/A	Odometer	9 069 km
Model	DS 7 PLUG-IN HYBRID AWD 360 PERFORMANCE	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond



Removable element

Spare wheel kit	✓


Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres

Michelin 245/35/21 Y Summer 6.0 mm

Michelin 245/35/21 Y Summer 6.0 mm




Michelin 245/35/21 Y Summer 6.0 mm

Michelin 245/35/21 Y Summer 6.0 mm




Exterior

1



Part	Tyre
Position	Front right
Damages	Cut
Comments	-

2



Part	Special rim 21"
Position	Front right
Damages	Scratched
Comments	-

4



Part	Bumper
Position	Front left
Damages	Scratched
Comments	-

5



Part	Wing moulding
Position	Front left
Damages	Scratched
Comments	-

6



Part	Exterior cleaning
Position	-
Damages	Not carried out
Comments	-

7



Part	Special rim 21"
Position	Front left
Damages	Scratched
Comments	-

8



Part	Special rim 21"
Position	Back left
Damages	Scratched
Comments	-

9



Part	Bumper
Position	Back
Damages	Scratched
Comments	-

10



Part	Tyre
Position	Back left
Damages	Cut
Comments	-

12



Part	Special rim 21"
Position	Back right
Damages	Scratched
Comments	-

Interior damage

3



Part	Interior cleaning
Position	-
Damages	Not carried out
Comments	-

11



Part	Interior tailgate lining
Position	-
Damages	Scratched
Comments	-